



超飛實業股份有限公司

MTH HOBBY PRODUCTS INDUSTRIAL CO., LTD.

SUPER FLYING MODEL

3F, No. 185-1, 38th Road, Taichung Ind Park, Taichung 407, Taiwan, R.O.C.

Web: www.mth.com.tw Email: mthhobby@mth.com.tw

SF 無刷馬達說明書

INSTRUCTION FOR BRUSHLESS MOTOR

IMPORTANT 注意事項

PLEASE READ ALL OF THESE INSTRUCTIONS BEFORE USING BRUSHLESS MOTOR.

使用前請詳閱表格及說明。

- 1.) THE AC MOTORS ARE BRUSHLESS MOTOR, THEY REQUIRE A SENSORLESS ELECTRONIC SPEED CONTROL (ESC). DO NOT USE BRUSHED ESC!
此馬達為 AC 無刷馬達，請務必使用無刷變速器
- 2.) WHEN USE DIFFERENT SIZE PROPELLER, DO NOT OVERLOAD THE MAX CURRENT. IT IS BETTER TO TEST WITH THE SF DC AMPS & VOLTS METER.
使用其它規格螺旋槳時，最大電流請勿超載，建議連接電流電壓表測試
- 3.) CUT THE OPPOSITE BLADE OF 3 PCS, THEN IT CAN USE FOR 2 POLE BRUSHLESS TO ACHIEVE THE GREATEST EFFICIENCY.
導風扇葉片，可用斜口鉗從根部剪去對應的 3 葉，即可將 6 葉改為 3 葉，即可用於 2 極無刷馬達，達到最大效率
- 4.) PLEASE DON'T CLOSE TO ANY METAL PRODUCTS, SUCH AS THE SCREW, NAIL.
請勿靠近任何金屬物品，如螺絲、鐵釘。

Brushless Motors 9 Pole Outrunner 外轉無刷馬達 9 極 (Weight: 46g)

Motor 型號	No load/v RPM 轉速	No load/v Current 電流	Max Amps	Shaft dia
2200-9-3500	3500	10V/1.6A	22A	2.3mm
2200-9-1300	1300	0.9A	16A	3.0mm
2200-9-900	900	0.53A	15A	3.0mm